




FIG. 1



FEB 23 2004





FEB 23 2004

FIG. 2






FIG. 3

301 Customer ID	302 Name	303 Postal Code	304 Address	305 Phone Number	306 Floor Plan
00078723	Katsue Isono	123 -4567	Kadomatsu-cho 1-1, Kadomatsu-shi	06(6378) 5678	00078723m1 00078723m2
00078724	Makio Isobe	234 -0056	Moriguchi-cho 2-22, Morita-shi	078(81) 1234	00078724m1

FEB 23 2004



FEB 23 2004

FIG. 4

400

202		301		203		204		401
Appliance ID	Customer ID	Manufacturer Code		Model Code		Connection Point		
000001	00078723	0034		PQ01-83		1K01		
000002	03990212	0034		TV03-05		1L16		
000003	00078723	0034		PQ01-83		2L05		



FIG. 5

FEB 23 2004






FIG. 6

FEB 23 2004







FIG. 7

FEB 23 2004





FEB 23 2004

FIG. 8


Operation Mode	Temperature Difference $\Delta T$	Preset Temperature Reaching Time $\Delta t$	Compressor Rotational Frequency
Cooling	2.3	6.0	2000
Cooling	5.0	10.7	2210
Cooling	3.2	6.8	2033
Cooling	3.3	6.9	2008
Heating	3.5	3.7	2039
Heating	5.5	5.0	2157
Heating	3.0	3.5	2001
Heating	2.0	3.0	1899
Heating	2.2	3.0	1948
Heating	3.6	3.7	2030
Heating	4.8	4.5	2074
Heating	2.5	2.9	1975





FEB 23 2004

FIG. 9





FEB 23 2004

FIG. 10







FIG. 11A



FEB 23 2004

FIG. 11B

Failure Information	
Customer:	Katsue Isono
Address:	Kadomatsu-cho1-1, Kadomatsu-shi
Phone Number:	06-6378-5678
Location:	1F Kitchen(1K01)
Manufacturer Code:	034
Mode Code:	PQ01-83
Appliance ID:	000001
Abnormal Component:	Compressor
Abnormal Code:	PQX-822
Part Code:	PQP-07, PQS-15

Sketch:	1F, Ms. Isono's House
---------	-----------------------